

10.02.2015 20:44:14: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:14: NibeRS485: Sending ACK
10.02.2015 20:44:14: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:14: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:14: NibeRS485: Sending ACK
10.02.2015 20:44:14: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:14: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:14: NibeRS485: Ignoring
10.02.2015 20:44:15: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:15: NibeRS485: Ignoring
10.02.2015 20:44:15: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:15: NibeRS485: Sending ACK
10.02.2015 20:44:15: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:15: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:15: NibeRS485: Sending ACK
10.02.2015 20:44:15: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:15: NibeRS485: Received:
5C 00 20 68 50 93 9C 48 00 94 9C 00 00 91 9C 18
00 92 9C 00 00 8F 9C 07 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 54

10.02.2015 20:44:15: NibeRS485: Sending ACK
10.02.2015 20:44:15: NibeRS485: Got data for id 40083: 0x0048
10.02.2015 20:44:15: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:15: NibeRS485: Got data for id 40081: 0x0018
10.02.2015 20:44:15: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:15: NibeRS485: Got data for id 40079: 0x0007
10.02.2015 20:44:15: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:15: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:15: NibeRS485: Ignoring
10.02.2015 20:44:15: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:15: NibeRS485: No data found with id 40004
10.02.2015 20:44:16: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:16: NibeRS485: Ignoring

```
10.02.2015 20:44:16: NibeRS485: Received:
5C 00 20 6B 00 4B
```

5C 00 29 90 00 B9

10.02.2015 20:44:17: NibeRS485: Ignoring

10.02.2015 20:44:17: TaloLoggerThreadStore: Storing logged data with 2 points.

10.02.2015 20:44:17: TaloLoggerThreadStore: Logged data for timestamp 20150210204415

dummy: 12.3

nibeoutdoor: 3.0

10.02.2015 20:44:18: NibeRS485: Received:

5C 00 29 55 02 08 00 76

10.02.2015 20:44:18: NibeRS485: Ignoring

10.02.2015 20:44:18: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:44:18: NibeRS485: Sending ACK

10.02.2015 20:44:18: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:44:18: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:44:18: NibeRS485: Sending ACK

10.02.2015 20:44:18: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:44:18: NibeRS485: Received:

5C 00 29 90 00 B9

10.02.2015 20:44:18: NibeRS485: Ignoring

10.02.2015 20:44:19: NibeRS485: Received:

5C 00 29 55 02 08 00 76

10.02.2015 20:44:19: NibeRS485: Ignoring

10.02.2015 20:44:19: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:44:19: NibeRS485: Sending ACK

10.02.2015 20:44:19: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:44:19: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:44:19: NibeRS485: Sending ACK

10.02.2015 20:44:19: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:44:19: NibeRS485: Received:

5C 00 20 68 50 93 9C 39 00 94 9C 00 00 91 9C 12

00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00

00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 24

10.02.2015 20:44:19: NibeRS485: Sending ACK

10.02.2015 20:44:19: NibeRS485: Got data for id 40083: 0x0039

10.02.2015 20:44:19: NibeRS485: Got data for id 40084: 0x0000

10.02.2015 20:44:19: NibeRS485: Got data for id 40081: 0x0012

10.02.2015 20:44:19: NibeRS485: Got data for id 40082: 0x0000

10.02.2015 20:44:19: NibeRS485: Got data for id 40079: 0x000C

10.02.2015 20:44:19: NibeRS485: Got data for id 40080: 0x0000

10.02.2015 20:44:19: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:44:19: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:44:19: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:44:19: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:44:19: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:44:19: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:44:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:19: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:19: NibeRS485: Ignoring
10.02.2015 20:44:20: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:20: NibeRS485: Ignoring
10.02.2015 20:44:20: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:20: NibeRS485: Sending ACK
10.02.2015 20:44:20: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:20: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:20: NibeRS485: Sending ACK
10.02.2015 20:44:20: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:20: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:20: NibeRS485: Ignoring
10.02.2015 20:44:20: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:20: NibeRS485: No data found with id 40004
10.02.2015 20:44:21: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:21: NibeRS485: Ignoring
10.02.2015 20:44:21: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:21: NibeRS485: Sending ACK
10.02.2015 20:44:21: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:21: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:21: NibeRS485: No data found with id 40004
10.02.2015 20:44:21: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:21: NibeRS485: Sending ACK
10.02.2015 20:44:21: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:21: NibeRS485: Received:
5C 00 20 68 50 93 9C 39 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 24

10.02.2015 20:44:21: NibeRS485: Sending ACK
10.02.2015 20:44:21: NibeRS485: Got data for id 40083: 0x0039
10.02.2015 20:44:21: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:21: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:44:21: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:21: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:44:21: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:21: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:44:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:21: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:21: NibeRS485: Ignoring
10.02.2015 20:44:22: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:22: NibeRS485: Ignoring
10.02.2015 20:44:22: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:44:22: NibeRS485: Sending ACK
10.02.2015 20:44:22: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:44:22: NibeRS485: Received:
5C 00 20 6B 00 4B
10.02.2015 20:44:22: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:22: NibeRS485: No data found with id 40004

10.02.2015 20:44:22: NibeRS485: Sending ACK
10.02.2015 20:44:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:22: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:22: NibeRS485: Sending ACK
10.02.2015 20:44:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:22: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:44:22: NibeRS485: Sending ACK
10.02.2015 20:44:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:22: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:22: NibeRS485: Ignoring
10.02.2015 20:44:22: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:44:22: NibeRS485: Sending ACK
10.02.2015 20:44:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:22: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:44:22: NibeRS485: Sending ACK
10.02.2015 20:44:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:22: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:44:22: TaloLoggerThreadStore: Logged data for timestamp 20150210204420
dummy: 12.3
nibeoutdoor: 3.0
10.02.2015 20:44:23: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:23: NibeRS485: Ignoring
10.02.2015 20:44:23: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:23: NibeRS485: Sending ACK

10.02.2015 20:44:23: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:23: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:23: NibeRS485: Sending ACK
10.02.2015 20:44:23: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:23: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:23: NibeRS485: Ignoring
10.02.2015 20:44:24: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:24: NibeRS485: Ignoring
10.02.2015 20:44:24: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:24: NibeRS485: Sending ACK
10.02.2015 20:44:24: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:24: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:24: NibeRS485: Sending ACK
10.02.2015 20:44:24: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:24: NibeRS485: Received:
5C 00 20 68 50 93 9C 39 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 24

10.02.2015 20:44:24: NibeRS485: Sending ACK
10.02.2015 20:44:24: NibeRS485: Got data for id 40083: 0x0039
10.02.2015 20:44:24: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:24: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:44:24: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:24: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:44:24: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:24: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:24: NibeRS485: Ignoring
10.02.2015 20:44:25: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:25: NibeRS485: Ignoring
10.02.2015 20:44:25: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:25: NibeRS485: Sending ACK
10.02.2015 20:44:25: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:25: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:44:25: NibeRS485: Sending ACK
10.02.2015 20:44:25: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:25: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:25: NibeRS485: Ignoring
10.02.2015 20:44:25: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:25: NibeRS485: No data found with id 40004
10.02.2015 20:44:26: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:26: NibeRS485: Ignoring
10.02.2015 20:44:26: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:26: NibeRS485: Sending ACK
10.02.2015 20:44:26: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:26: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:26: NibeRS485: No data found with id 40004
10.02.2015 20:44:26: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:26: NibeRS485: Sending ACK
10.02.2015 20:44:26: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:26: NibeRS485: Received:
5C 00 20 68 50 93 9C 45 00 94 9C 00 00 91 9C 19
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 56

10.02.2015 20:44:26: NibeRS485: Sending ACK
10.02.2015 20:44:26: NibeRS485: Got data for id 40083: 0x0045
10.02.2015 20:44:26: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:26: NibeRS485: Got data for id 40081: 0x0019
10.02.2015 20:44:26: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:26: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:44:26: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:26: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:26: NibeRS485: Ignoring
10.02.2015 20:44:27: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:27: NibeRS485: Ignoring
10.02.2015 20:44:27: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:44:27: NibeRS485: Sending ACK

[illegible]

10.02.2015 20:44:28: NibeRS485: Ignoring
10.02.2015 20:44:29: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:29: NibeRS485: Ignoring
10.02.2015 20:44:29: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:29: NibeRS485: Sending ACK
10.02.2015 20:44:29: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:29: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:29: NibeRS485: Sending ACK
10.02.2015 20:44:29: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:29: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:29: NibeRS485: Ignoring
10.02.2015 20:44:30: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:30: NibeRS485: Ignoring
10.02.2015 20:44:30: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:30: NibeRS485: Sending ACK
10.02.2015 20:44:30: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:30: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:30: NibeRS485: Sending ACK
10.02.2015 20:44:30: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:30: NibeRS485: Received:
5C 00 20 68 50 93 9C 3E 00 94 9C 00 00 91 9C 14
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 20

10.02.2015 20:44:30: NibeRS485: Sending ACK
10.02.2015 20:44:30: NibeRS485: Got data for id 40083: 0x003E
10.02.2015 20:44:30: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:30: NibeRS485: Got data for id 40081: 0x0014
10.02.2015 20:44:30: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:30: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:44:30: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:30: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:30: NibeRS485: Ignoring
10.02.2015 20:44:30: NibeRS485: Running nibeBus query with id 40004

[illegible]

10.02.2015 20:44:32: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:32: NibeRS485: Ignoring
10.02.2015 20:44:32: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:44:32: NibeRS485: Sending ACK
10.02.2015 20:44:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:32: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:44:32: NibeRS485: Sending ACK
10.02.2015 20:44:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:32: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:32: NibeRS485: Ignoring
10.02.2015 20:44:32: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:44:32: TaloLoggerThreadStore: Logged data for timestamp 20150210204430
dummy: 12.2
nibeoutdoor: 3.0

10.02.2015 20:44:33: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:33: NibeRS485: Ignoring
10.02.2015 20:44:33: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:33: NibeRS485: Sending ACK
10.02.2015 20:44:33: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:33: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:33: NibeRS485: Sending ACK
10.02.2015 20:44:33: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:33: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:33: NibeRS485: Ignoring
10.02.2015 20:44:34: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:34: NibeRS485: Ignoring
10.02.2015 20:44:34: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:34: NibeRS485: Sending ACK
10.02.2015 20:44:34: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:34: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:34: NibeRS485: Sending ACK
10.02.2015 20:44:34: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:34: NibeRS485: Received:
5C 00 20 68 50 93 9C 38 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 25

10.02.2015 20:44:34: NibeRS485: Sending ACK
10.02.2015 20:44:34: NibeRS485: Got data for id 40083: 0x0038
10.02.2015 20:44:34: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:34: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:44:34: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:34: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:44:34: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:34: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:34: NibeRS485: Ignoring
10.02.2015 20:44:35: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:35: NibeRS485: Ignoring
10.02.2015 20:44:35: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:35: NibeRS485: Sending ACK
10.02.2015 20:44:35: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:35: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:35: NibeRS485: Sending ACK
10.02.2015 20:44:35: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:35: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:35: NibeRS485: Ignoring
10.02.2015 20:44:35: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:35: NibeRS485: No data found with id 40004
10.02.2015 20:44:36: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:36: NibeRS485: Ignoring
10.02.2015 20:44:36: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:36: NibeRS485: Sending ACK
10.02.2015 20:44:36: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:36: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:36: NibeRS485: No data found with id 40004
10.02.2015 20:44:36: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:36: NibeRS485: Sending ACK
10.02.2015 20:44:36: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:36: NibeRS485: Received:
5C 00 20 68 50 93 9C 4B 00 94 9C 00 00 91 9C 19
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 58

10.02.2015 20:44:36: NibeRS485: Sending ACK
10.02.2015 20:44:36: NibeRS485: Got data for id 40083: 0x004B
10.02.2015 20:44:36: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:36: NibeRS485: Got data for id 40081: 0x0019
10.02.2015 20:44:36: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:36: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:44:36: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:36: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:36: NibeRS485: Ignoring
10.02.2015 20:44:37: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:37: NibeRS485: Ignoring
10.02.2015 20:44:37: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:44:37: NibeRS485: Sending ACK
10.02.2015 20:44:37: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:44:37: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:37: NibeRS485: Sending ACK
10.02.2015 20:44:37: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:37: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:37: NibeRS485: Sending ACK
10.02.2015 20:44:37: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:37: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:37: NibeRS485: No data found with id 40004
10.02.2015 20:44:37: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:44:37: NibeRS485: Sending ACK
10.02.2015 20:44:37: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:37: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:37: NibeRS485: Ignoring
10.02.2015 20:44:37: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:44:37: TaloLoggerThreadStore: Logged data for timestamp 20150210204435
dummy: 12.2
nibeoutdoor: 3.0
10.02.2015 20:44:38: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:38: NibeRS485: Ignoring
10.02.2015 20:44:38: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:38: NibeRS485: Sending ACK
10.02.2015 20:44:38: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:38: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:38: NibeRS485: Sending ACK
10.02.2015 20:44:38: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:38: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:38: NibeRS485: Ignoring
10.02.2015 20:44:39: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:39: NibeRS485: Ignoring
10.02.2015 20:44:39: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:39: NibeRS485: Sending ACK
10.02.2015 20:44:39: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:39: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:39: NibeRS485: Sending ACK
10.02.2015 20:44:39: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:39: NibeRS485: Received:
5C 00 20 68 50 93 9C 35 00 94 9C 00 00 91 9C 11
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2E

10.02.2015 20:44:39: NibeRS485: Sending ACK
10.02.2015 20:44:39: NibeRS485: Got data for id 40083: 0x0035
10.02.2015 20:44:39: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:39: NibeRS485: Got data for id 40081: 0x0011
10.02.2015 20:44:39: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:39: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:44:39: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:39: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:39: NibeRS485: Ignoring
10.02.2015 20:44:40: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:40: NibeRS485: Ignoring
10.02.2015 20:44:40: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:44:40: NibeRS485: Sending ACK
10.02.2015 20:44:40: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:40: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:40: NibeRS485: Sending ACK
10.02.2015 20:44:40: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:40: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:40: NibeRS485: Ignoring
10.02.2015 20:44:40: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:40: NibeRS485: No data found with id 40004
10.02.2015 20:44:41: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:41: NibeRS485: Ignoring
10.02.2015 20:44:41: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:41: NibeRS485: Sending ACK
10.02.2015 20:44:41: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:41: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:41: NibeRS485: No data found with id 40004
10.02.2015 20:44:41: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:41: NibeRS485: Sending ACK
10.02.2015 20:44:41: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:41: NibeRS485: Received:
5C 00 20 68 50 93 9C 3A 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0B 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 21

10.02.2015 20:44:41: NibeRS485: Sending ACK
10.02.2015 20:44:41: NibeRS485: Got data for id 40083: 0x003A
10.02.2015 20:44:41: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:41: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:44:41: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:41: NibeRS485: Got data for id 40079: 0x000B
10.02.2015 20:44:41: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:41: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:41: NibeRS485: Ignoring
10.02.2015 20:44:42: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:42: NibeRS485: Ignoring
10.02.2015 20:44:42: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1F 00 00 00 8B

10.02.2015 20:44:42: NibeRS485: Sending ACK
10.02.2015 20:44:42: NibeRS485: Got queried data for id 40004: 0x001F
10.02.2015 20:44:42: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:42: NibeRS485: Sending ACK
10.02.2015 20:44:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:42: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:42: NibeRS485: Sending ACK
10.02.2015 20:44:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:42: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:42: NibeRS485: Ignoring
10.02.2015 20:44:42: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:42: NibeRS485: No data found with id 40004
10.02.2015 20:44:42: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:44:42: NibeRS485: Sending ACK
10.02.2015 20:44:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:42: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:44:42: NibeRS485: Sending ACK
10.02.2015 20:44:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:42: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:44:42: TaloLoggerThreadStore: Logged data for timestamp 20150210204440
dummy: 12.2
nibeoutdoor: 3.1
10.02.2015 20:44:43: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:43: NibeRS485: Ignoring
10.02.2015 20:44:43: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:43: NibeRS485: Sending ACK
10.02.2015 20:44:43: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:43: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:43: NibeRS485: Sending ACK
10.02.2015 20:44:43: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:43: NibeRS485: Received:
5C 00 20 68 50 93 9C 36 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2F

10.02.2015 20:44:43: NibeRS485: Sending ACK
10.02.2015 20:44:43: NibeRS485: Got data for id 40083: 0x0036

10.02.2015 20:44:43: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:43: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:44:43: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:43: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:44:43: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:43: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:43: NibeRS485: Ignoring
10.02.2015 20:44:44: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:44: NibeRS485: Ignoring
10.02.2015 20:44:44: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:44: NibeRS485: Sending ACK
10.02.2015 20:44:44: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:44: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:44: NibeRS485: Sending ACK
10.02.2015 20:44:44: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:44: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:44: NibeRS485: Ignoring
10.02.2015 20:44:45: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:45: NibeRS485: Ignoring
10.02.2015 20:44:45: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:45: NibeRS485: Sending ACK
10.02.2015 20:44:45: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:45: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:45: NibeRS485: Sending ACK
10.02.2015 20:44:45: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:45: NibeRS485: Received:
5C 00 20 68 50 93 9C 4E 00 94 9C 00 00 91 9C 18
00 92 9C 00 00 8F 9C 08 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 5D

10.02.2015 20:44:45: NibeRS485: Sending ACK
10.02.2015 20:44:45: NibeRS485: Got data for id 40083: 0x004E
10.02.2015 20:44:45: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:45: NibeRS485: Got data for id 40081: 0x0018

10.02.2015 20:44:45: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:45: NibeRS485: Got data for id 40079: 0x0008
10.02.2015 20:44:45: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:45: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:45: NibeRS485: Ignoring
10.02.2015 20:44:45: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:45: NibeRS485: No data found with id 40004
10.02.2015 20:44:46: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:46: NibeRS485: Ignoring
10.02.2015 20:44:46: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:46: NibeRS485: Sending ACK
10.02.2015 20:44:46: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:46: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:46: NibeRS485: No data found with id 40004
10.02.2015 20:44:46: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:46: NibeRS485: Sending ACK
10.02.2015 20:44:46: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:46: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:46: NibeRS485: Ignoring
10.02.2015 20:44:47: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1F 00 00 00 8B

10.02.2015 20:44:47: NibeRS485: Sending ACK
10.02.2015 20:44:47: NibeRS485: Got queried data for id 40004: 0x001F
10.02.2015 20:44:47: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:47: NibeRS485: Sending ACK
10.02.2015 20:44:47: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:47: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:47: NibeRS485: Sending ACK
10.02.2015 20:44:47: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:47: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:47: NibeRS485: No data found with id 40004
10.02.2015 20:44:47: NibeRS485: Received:
5C 00 20 68 50 93 9C 39 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0B 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 23

10.02.2015 20:44:47: NibeRS485: Sending ACK
10.02.2015 20:44:47: NibeRS485: Got data for id 40083: 0x0039
10.02.2015 20:44:47: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:47: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:44:47: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:47: NibeRS485: Got data for id 40079: 0x000B
10.02.2015 20:44:47: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:47: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:47: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:47: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:47: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:47: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:47: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:47: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:47: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:47: NibeRS485: Ignoring
10.02.2015 20:44:47: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:47: NibeRS485: Ignoring
10.02.2015 20:44:47: TalLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:44:47: TalLoggerThreadStore: Logged data for timestamp 20150210204445
dummy: 12.2
nibeoutdoor: 3.1
10.02.2015 20:44:48: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:48: NibeRS485: Ignoring
10.02.2015 20:44:48: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:48: NibeRS485: Sending ACK
10.02.2015 20:44:48: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:48: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:48: NibeRS485: Sending ACK
10.02.2015 20:44:48: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:48: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:48: NibeRS485: Ignoring
10.02.2015 20:44:49: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:49: NibeRS485: Ignoring
10.02.2015 20:44:49: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:49: NibeRS485: Sending ACK
10.02.2015 20:44:49: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:49: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:49: NibeRS485: Sending ACK
10.02.2015 20:44:49: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:49: NibeRS485: Received:

5C 00 20 68 50 93 9C 3A 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0D 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 26

10.02.2015 20:44:49: NibeRS485: Sending ACK
10.02.2015 20:44:49: NibeRS485: Got data for id 40083: 0x003A
10.02.2015 20:44:49: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:49: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:44:49: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:49: NibeRS485: Got data for id 40079: 0x000D
10.02.2015 20:44:49: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:49: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:49: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:49: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:49: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:49: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:49: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:49: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:49: NibeRS485: Ignoring
10.02.2015 20:44:50: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:50: NibeRS485: Ignoring
10.02.2015 20:44:50: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:50: NibeRS485: Sending ACK
10.02.2015 20:44:50: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:50: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:50: NibeRS485: Sending ACK
10.02.2015 20:44:50: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:50: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:50: NibeRS485: Ignoring
10.02.2015 20:44:50: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:50: NibeRS485: No data found with id 40004
10.02.2015 20:44:51: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:51: NibeRS485: Ignoring
10.02.2015 20:44:51: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:51: NibeRS485: Sending ACK
10.02.2015 20:44:51: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:51: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:51: NibeRS485: No data found with id 40004
10.02.2015 20:44:51: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:51: NibeRS485: Sending ACK

10.02.2015 20:44:51: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:51: NibeRS485: Received:
5C 00 20 68 50 93 9C 3A 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0A 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 21

10.02.2015 20:44:51: NibeRS485: Sending ACK
10.02.2015 20:44:51: NibeRS485: Got data for id 40083: 0x003A
10.02.2015 20:44:51: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:51: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:44:51: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:51: NibeRS485: Got data for id 40079: 0x000A
10.02.2015 20:44:51: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:51: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:51: NibeRS485: Ignoring
10.02.2015 20:44:52: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:52: NibeRS485: Ignoring
10.02.2015 20:44:52: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:44:52: NibeRS485: Sending ACK
10.02.2015 20:44:52: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:44:52: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:52: NibeRS485: Sending ACK
10.02.2015 20:44:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:52: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:52: NibeRS485: Sending ACK
10.02.2015 20:44:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:52: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:52: NibeRS485: No data found with id 40004
10.02.2015 20:44:52: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:44:52: NibeRS485: Sending ACK
10.02.2015 20:44:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:52: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:52: NibeRS485: Ignoring
10.02.2015 20:44:52: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:44:52: NibeRS485: Sending ACK
10.02.2015 20:44:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:52: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:44:52: NibeRS485: Sending ACK
10.02.2015 20:44:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:52: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:44:52: TaloLoggerThreadStore: Logged data for timestamp 20150210204450
dummy: 12.1
nibeoutdoor: 3.0
10.02.2015 20:44:53: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:53: NibeRS485: Ignoring
10.02.2015 20:44:53: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:53: NibeRS485: Sending ACK
10.02.2015 20:44:53: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:53: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:53: NibeRS485: Sending ACK
10.02.2015 20:44:53: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:53: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:53: NibeRS485: Ignoring
10.02.2015 20:44:54: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:54: NibeRS485: Ignoring
10.02.2015 20:44:54: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:54: NibeRS485: Sending ACK
10.02.2015 20:44:54: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:54: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:54: NibeRS485: Sending ACK
10.02.2015 20:44:54: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:54: NibeRS485: Received:
5C 00 20 68 50 93 9C 3B 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 26

10.02.2015 20:44:54: NibeRS485: Sending ACK
10.02.2015 20:44:54: NibeRS485: Got data for id 40083: 0x003B
10.02.2015 20:44:54: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:54: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:44:54: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:54: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:44:54: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:54: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:44:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:54: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:54: NibeRS485: Ignoring
10.02.2015 20:44:55: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:55: NibeRS485: Ignoring
10.02.2015 20:44:55: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:55: NibeRS485: Sending ACK
10.02.2015 20:44:55: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:55: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:55: NibeRS485: Sending ACK
10.02.2015 20:44:55: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:55: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:55: NibeRS485: Ignoring
10.02.2015 20:44:55: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:55: NibeRS485: No data found with id 40004
10.02.2015 20:44:56: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:56: NibeRS485: Ignoring
10.02.2015 20:44:56: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:56: NibeRS485: Sending ACK
10.02.2015 20:44:56: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:56: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:56: NibeRS485: No data found with id 40004
10.02.2015 20:44:56: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:56: NibeRS485: Sending ACK
10.02.2015 20:44:56: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:56: NibeRS485: Received:
5C 00 20 68 50 93 9C 3A 00 94 9C 00 00 91 9C 14
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 24

10.02.2015 20:44:56: NibeRS485: Sending ACK
10.02.2015 20:44:56: NibeRS485: Got data for id 40083: 0x003A
10.02.2015 20:44:56: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:56: NibeRS485: Got data for id 40081: 0x0014
10.02.2015 20:44:56: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:56: NibeRS485: Got data for id 40079: 0x0009

10.02.2015 20:44:56: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:56: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:56: NibeRS485: Ignoring
10.02.2015 20:44:57: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:57: NibeRS485: Ignoring
10.02.2015 20:44:57: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:44:57: NibeRS485: Sending ACK
10.02.2015 20:44:57: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:44:57: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:57: NibeRS485: Sending ACK
10.02.2015 20:44:57: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:57: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:57: NibeRS485: Sending ACK
10.02.2015 20:44:57: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:57: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:57: NibeRS485: Ignoring
10.02.2015 20:44:57: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:44:57: NibeRS485: No data found with id 40004
10.02.2015 20:44:57: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:44:57: TaloLoggerThreadStore: Logged data for timestamp 20150210204455
dummy: 12.1
nibeoutdoor: 3.0
10.02.2015 20:44:58: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:58: NibeRS485: Ignoring
10.02.2015 20:44:58: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:58: NibeRS485: Sending ACK
10.02.2015 20:44:58: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:58: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:58: NibeRS485: Sending ACK
10.02.2015 20:44:58: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:58: NibeRS485: Received:
5C 00 20 68 50 93 9C 40 00 94 9C 00 00 91 9C 16
00 92 9C 00 00 8F 9C 08 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 5D

10.02.2015 20:44:58: NibeRS485: Sending ACK
10.02.2015 20:44:58: NibeRS485: Got data for id 40083: 0x0040
10.02.2015 20:44:58: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:44:58: NibeRS485: Got data for id 40081: 0x0016
10.02.2015 20:44:58: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:44:58: NibeRS485: Got data for id 40079: 0x0008
10.02.2015 20:44:58: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:44:58: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:58: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:58: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:58: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:58: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:58: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:44:58: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:58: NibeRS485: Ignoring
10.02.2015 20:44:59: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:44:59: NibeRS485: Ignoring
10.02.2015 20:44:59: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:44:59: NibeRS485: Sending ACK
10.02.2015 20:44:59: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:59: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:44:59: NibeRS485: Sending ACK
10.02.2015 20:44:59: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:44:59: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:44:59: NibeRS485: Ignoring
10.02.2015 20:45:00: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:00: NibeRS485: Ignoring
10.02.2015 20:45:00: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:00: NibeRS485: Sending ACK
10.02.2015 20:45:00: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:00: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:00: NibeRS485: Sending ACK
10.02.2015 20:45:00: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:00: NibeRS485: Received:
5C 00 20 68 50 93 9C 40 00 94 9C 00 00 91 9C 16
00 92 9C 00 00 8F 9C 08 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 5D

10.02.2015 20:45:00: NibeRS485: Sending ACK
10.02.2015 20:45:00: NibeRS485: Got data for id 40083: 0x0040
10.02.2015 20:45:00: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:00: NibeRS485: Got data for id 40081: 0x0016
10.02.2015 20:45:00: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:00: NibeRS485: Got data for id 40079: 0x0008
10.02.2015 20:45:00: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:00: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:00: NibeRS485: Ignoring
10.02.2015 20:45:00: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:00: NibeRS485: No data found with id 40004
10.02.2015 20:45:01: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:01: NibeRS485: Ignoring
10.02.2015 20:45:01: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:01: NibeRS485: Sending ACK
10.02.2015 20:45:01: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:01: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:01: NibeRS485: No data found with id 40004
10.02.2015 20:45:01: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:01: NibeRS485: Sending ACK
10.02.2015 20:45:01: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:01: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:01: NibeRS485: Ignoring
10.02.2015 20:45:02: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:02: NibeRS485: Ignoring
10.02.2015 20:45:02: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:45:02: NibeRS485: Sending ACK
10.02.2015 20:45:02: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:45:02: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:02: NibeRS485: Sending ACK
10.02.2015 20:45:02: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:02: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:02: NibeRS485: Sending ACK
10.02.2015 20:45:02: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:02: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:02: NibeRS485: No data found with id 40004
10.02.2015 20:45:02: NibeRS485: Received:
5C 00 20 68 50 93 9C 4B 00 94 9C 00 00 91 9C 19
00 92 9C 00 00 8F 9C 07 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 56

10.02.2015 20:45:02: NibeRS485: Sending ACK
10.02.2015 20:45:02: NibeRS485: Got data for id 40083: 0x004B
10.02.2015 20:45:02: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:02: NibeRS485: Got data for id 40081: 0x0019
10.02.2015 20:45:02: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:02: NibeRS485: Got data for id 40079: 0x0007
10.02.2015 20:45:02: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:02: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:02: NibeRS485: Ignoring
10.02.2015 20:45:02: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:02: NibeRS485: Sending ACK
10.02.2015 20:45:02: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:02: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:02: NibeRS485: Sending ACK
10.02.2015 20:45:02: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:02: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:02: TaloLoggerThreadStore: Logged data for timestamp 20150210204500
dummy: 12.1
nibeoutdoor: 3.0
10.02.2015 20:45:03: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:03: NibeRS485: Ignoring
10.02.2015 20:45:03: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:03: NibeRS485: Sending ACK
10.02.2015 20:45:03: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:03: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:03: NibeRS485: Sending ACK
10.02.2015 20:45:03: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:03: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:03: NibeRS485: Ignoring

10.02.2015 20:45:04: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:04: NibeRS485: Ignoring
10.02.2015 20:45:04: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:04: NibeRS485: Sending ACK
10.02.2015 20:45:04: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:04: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:04: NibeRS485: Sending ACK
10.02.2015 20:45:04: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:04: NibeRS485: Received:
5C 00 20 68 50 93 9C 4D 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0B 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 57

10.02.2015 20:45:04: NibeRS485: Sending ACK
10.02.2015 20:45:04: NibeRS485: Got data for id 40083: 0x004D
10.02.2015 20:45:04: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:04: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:45:04: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:04: NibeRS485: Got data for id 40079: 0x000B
10.02.2015 20:45:04: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:04: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:04: NibeRS485: Ignoring
10.02.2015 20:45:05: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:05: NibeRS485: Ignoring
10.02.2015 20:45:05: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:05: NibeRS485: Sending ACK
10.02.2015 20:45:05: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:05: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:05: NibeRS485: Sending ACK
10.02.2015 20:45:05: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:05: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:05: NibeRS485: Ignoring
10.02.2015 20:45:05: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:05: NibeRS485: No data found with id 40004

10.02.2015 20:45:06: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:06: NibeRS485: Ignoring
10.02.2015 20:45:06: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:06: NibeRS485: Sending ACK
10.02.2015 20:45:06: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:06: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:06: NibeRS485: No data found with id 40004
10.02.2015 20:45:06: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:06: NibeRS485: Sending ACK
10.02.2015 20:45:06: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:06: NibeRS485: Received:
5C 00 20 68 50 93 9C 47 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 5B

10.02.2015 20:45:06: NibeRS485: Sending ACK
10.02.2015 20:45:06: NibeRS485: Got data for id 40083: 0x0047
10.02.2015 20:45:06: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:06: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:45:06: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:06: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:45:06: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:06: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:06: NibeRS485: Ignoring
10.02.2015 20:45:07: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:07: NibeRS485: Ignoring
10.02.2015 20:45:07: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1F 00 00 00 8B

10.02.2015 20:45:07: NibeRS485: Sending ACK
10.02.2015 20:45:07: NibeRS485: Got queried data for id 40004: 0x001F
10.02.2015 20:45:07: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:07: NibeRS485: Sending ACK
10.02.2015 20:45:07: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:07: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:07: NibeRS485: Sending ACK

10.02.2015 20:45:07: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:07: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:45:07: NibeRS485: Sending ACK
10.02.2015 20:45:07: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:07: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:07: NibeRS485: No data found with id 40004
10.02.2015 20:45:07: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:07: NibeRS485: Ignoring
10.02.2015 20:45:07: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:07: TaloLoggerThreadStore: Logged data for timestamp 20150210204505
dummy: 12.0
nibeoutdoor: 3.1
10.02.2015 20:45:08: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:08: NibeRS485: Ignoring
10.02.2015 20:45:08: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:08: NibeRS485: Sending ACK
10.02.2015 20:45:08: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:08: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:08: NibeRS485: Sending ACK
10.02.2015 20:45:08: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:08: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:08: NibeRS485: Ignoring
10.02.2015 20:45:09: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:09: NibeRS485: Ignoring
10.02.2015 20:45:09: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:09: NibeRS485: Sending ACK
10.02.2015 20:45:09: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:09: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:09: NibeRS485: Sending ACK
10.02.2015 20:45:09: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:09: NibeRS485: Received:
5C 00 20 68 50 93 9C 61 00 94 9C 00 00 91 9C 18
00 92 9C 00 00 8F 9C 08 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 72

10.02.2015 20:45:09: NibeRS485: Sending ACK
10.02.2015 20:45:09: NibeRS485: Got data for id 40083: 0x0061
10.02.2015 20:45:09: NibeRS485: Got data for id 40084: 0x0000

10.02.2015 20:45:09: NibeRS485: Got data for id 40081: 0x0018
10.02.2015 20:45:09: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:09: NibeRS485: Got data for id 40079: 0x0008
10.02.2015 20:45:09: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:09: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:09: NibeRS485: Ignoring
10.02.2015 20:45:10: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:10: NibeRS485: Ignoring
10.02.2015 20:45:10: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:10: NibeRS485: Sending ACK
10.02.2015 20:45:10: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:10: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:10: NibeRS485: Sending ACK
10.02.2015 20:45:10: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:10: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:10: NibeRS485: Ignoring
10.02.2015 20:45:10: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:10: NibeRS485: No data found with id 40004
10.02.2015 20:45:11: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:11: NibeRS485: Ignoring
10.02.2015 20:45:11: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:11: NibeRS485: Sending ACK
10.02.2015 20:45:11: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:11: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:11: NibeRS485: No data found with id 40004
10.02.2015 20:45:11: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:11: NibeRS485: Sending ACK
10.02.2015 20:45:11: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:11: NibeRS485: Received:
5C 00 20 68 50 93 9C 4B 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 57

10.02.2015 20:45:11: NibeRS485: Sending ACK

10.02.2015 20:45:11: NibeRS485: Got data for id 40083: 0x004B
10.02.2015 20:45:11: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:11: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:45:11: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:11: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:45:11: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:11: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:11: NibeRS485: Ignoring
10.02.2015 20:45:12: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:12: NibeRS485: Ignoring
10.02.2015 20:45:12: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:45:12: NibeRS485: Sending ACK
10.02.2015 20:45:12: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:45:12: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:12: NibeRS485: Sending ACK
10.02.2015 20:45:12: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:12: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:12: NibeRS485: Sending ACK
10.02.2015 20:45:12: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:12: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:12: NibeRS485: Ignoring
10.02.2015 20:45:12: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:12: NibeRS485: No data found with id 40004
10.02.2015 20:45:12: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:12: NibeRS485: Sending ACK
10.02.2015 20:45:12: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:12: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:12: NibeRS485: Sending ACK
10.02.2015 20:45:12: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:12: TalLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:12: TalLoggerThreadStore: Logged data for timestamp 20150210204510
dummy: 12.0
nibeoutdoor: 3.0
10.02.2015 20:45:13: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:13: NibeRS485: Ignoring

10.02.2015 20:45:13: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:13: NibeRS485: Sending ACK
10.02.2015 20:45:13: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:13: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:13: NibeRS485: Sending ACK
10.02.2015 20:45:13: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:13: NibeRS485: Received:
5C 00 20 68 50 93 9C 48 00 94 9C 00 00 91 9C 15
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 52

10.02.2015 20:45:13: NibeRS485: Sending ACK
10.02.2015 20:45:13: NibeRS485: Got data for id 40083: 0x0048
10.02.2015 20:45:13: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:13: NibeRS485: Got data for id 40081: 0x0015
10.02.2015 20:45:13: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:13: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:45:13: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:13: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:13: NibeRS485: Ignoring
10.02.2015 20:45:14: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:14: NibeRS485: Ignoring
10.02.2015 20:45:14: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:14: NibeRS485: Sending ACK
10.02.2015 20:45:14: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:14: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:14: NibeRS485: Sending ACK
10.02.2015 20:45:14: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:14: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:14: NibeRS485: Ignoring
10.02.2015 20:45:15: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:15: NibeRS485: Ignoring
10.02.2015 20:45:15: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:15: NibeRS485: Sending ACK
10.02.2015 20:45:15: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:15: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:15: NibeRS485: Sending ACK
10.02.2015 20:45:15: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:15: NibeRS485: Received:
5C 00 20 68 50 93 9C 60 00 94 9C 00 00 91 9C 1A
00 92 9C 00 00 8F 9C 08 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 71

10.02.2015 20:45:15: NibeRS485: Sending ACK
10.02.2015 20:45:15: NibeRS485: Got data for id 40083: 0x0060
10.02.2015 20:45:15: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:15: NibeRS485: Got data for id 40081: 0x001A
10.02.2015 20:45:15: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:15: NibeRS485: Got data for id 40079: 0x0008
10.02.2015 20:45:15: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:15: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:15: NibeRS485: Ignoring
10.02.2015 20:45:15: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:15: NibeRS485: No data found with id 40004
10.02.2015 20:45:16: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:16: NibeRS485: Ignoring
10.02.2015 20:45:16: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:16: NibeRS485: Sending ACK
10.02.2015 20:45:16: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:16: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:16: NibeRS485: No data found with id 40004
10.02.2015 20:45:16: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:16: NibeRS485: Sending ACK
10.02.2015 20:45:16: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:16: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:16: NibeRS485: Ignoring
10.02.2015 20:45:17: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:45:17: NibeRS485: Sending ACK

10.02.2015 20:45:17: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:45:17: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:17: NibeRS485: Sending ACK
10.02.2015 20:45:17: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:17: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:17: NibeRS485: Sending ACK
10.02.2015 20:45:17: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:17: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:17: NibeRS485: No data found with id 40004
10.02.2015 20:45:17: NibeRS485: Received:
5C 00 20 68 50 93 9C 3A 00 94 9C 00 00 91 9C 14
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 21

10.02.2015 20:45:17: NibeRS485: Sending ACK
10.02.2015 20:45:17: NibeRS485: Got data for id 40083: 0x003A
10.02.2015 20:45:17: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:17: NibeRS485: Got data for id 40081: 0x0014
10.02.2015 20:45:17: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:17: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:45:17: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:17: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:17: NibeRS485: Ignoring
10.02.2015 20:45:17: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:17: NibeRS485: Ignoring
10.02.2015 20:45:17: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:17: TaloLoggerThreadStore: Logged data for timestamp 20150210204515
dummy: 12.0
nibeoutdoor: 3.0
10.02.2015 20:45:18: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:18: NibeRS485: Ignoring
10.02.2015 20:45:18: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:18: NibeRS485: Sending ACK
10.02.2015 20:45:18: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:18: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:18: NibeRS485: Sending ACK

10.02.2015 20:45:18: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:18: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:18: NibeRS485: Ignoring
10.02.2015 20:45:19: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:19: NibeRS485: Ignoring
10.02.2015 20:45:19: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:19: NibeRS485: Sending ACK
10.02.2015 20:45:19: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:19: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:19: NibeRS485: Sending ACK
10.02.2015 20:45:19: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:19: NibeRS485: Received:
5C 00 20 68 50 93 9C 4B 00 94 9C 00 00 91 9C 16
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 57

10.02.2015 20:45:19: NibeRS485: Sending ACK
10.02.2015 20:45:19: NibeRS485: Got data for id 40083: 0x004B
10.02.2015 20:45:19: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:19: NibeRS485: Got data for id 40081: 0x0016
10.02.2015 20:45:19: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:19: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:45:19: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:19: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:19: NibeRS485: Ignoring
10.02.2015 20:45:20: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:20: NibeRS485: Ignoring
10.02.2015 20:45:20: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:20: NibeRS485: Sending ACK
10.02.2015 20:45:20: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:20: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:20: NibeRS485: Sending ACK
10.02.2015 20:45:20: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:20: NibeRS485: Received:

5C 00 29 90 00 B9

10.02.2015 20:45:20: NibeRS485: Ignoring
10.02.2015 20:45:20: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:20: NibeRS485: No data found with id 40004
10.02.2015 20:45:21: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:21: NibeRS485: Ignoring
10.02.2015 20:45:21: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:21: NibeRS485: Sending ACK
10.02.2015 20:45:21: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:21: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:21: NibeRS485: No data found with id 40004
10.02.2015 20:45:21: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:21: NibeRS485: Sending ACK
10.02.2015 20:45:21: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:21: NibeRS485: Received:
5C 00 20 68 50 93 9C 4B 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 57

10.02.2015 20:45:21: NibeRS485: Sending ACK
10.02.2015 20:45:21: NibeRS485: Got data for id 40083: 0x004B
10.02.2015 20:45:21: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:21: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:45:21: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:21: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:45:21: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:21: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:21: NibeRS485: Ignoring
10.02.2015 20:45:22: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:22: NibeRS485: Ignoring
10.02.2015 20:45:22: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:45:22: NibeRS485: Sending ACK
10.02.2015 20:45:22: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:45:22: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:22: NibeRS485: Sending ACK

10.02.2015 20:45:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:22: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:22: NibeRS485: Sending ACK
10.02.2015 20:45:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:22: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:45:22: NibeRS485: Sending ACK
10.02.2015 20:45:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:22: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:22: NibeRS485: No data found with id 40004
10.02.2015 20:45:22: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:22: NibeRS485: Ignoring
10.02.2015 20:45:22: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:22: NibeRS485: Sending ACK
10.02.2015 20:45:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:22: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:22: NibeRS485: Sending ACK
10.02.2015 20:45:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:22: TalLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:23: TalLoggerThreadStore: Logged data for timestamp 20150210204520
dummy: 11.9
nibeoutdoor: 3.0
10.02.2015 20:45:23: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:23: NibeRS485: Ignoring
10.02.2015 20:45:23: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:23: NibeRS485: Sending ACK
10.02.2015 20:45:23: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:23: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:23: NibeRS485: Sending ACK
10.02.2015 20:45:23: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:23: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:23: NibeRS485: Ignoring
10.02.2015 20:45:24: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:24: NibeRS485: Ignoring
10.02.2015 20:45:24: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:24: NibeRS485: Sending ACK
10.02.2015 20:45:24: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:24: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:45:24: NibeRS485: Sending ACK

10.02.2015 20:45:24: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:24: NibeRS485: Received:

5C 00 20 68 50 93 9C 3B 00 94 9C 00 00 91 9C 11
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 20

10.02.2015 20:45:24: NibeRS485: Sending ACK

10.02.2015 20:45:24: NibeRS485: Got data for id 40083: 0x003B

10.02.2015 20:45:24: NibeRS485: Got data for id 40084: 0x0000

10.02.2015 20:45:24: NibeRS485: Got data for id 40081: 0x0011

10.02.2015 20:45:24: NibeRS485: Got data for id 40082: 0x0000

10.02.2015 20:45:24: NibeRS485: Got data for id 40079: 0x0009

10.02.2015 20:45:24: NibeRS485: Got data for id 40080: 0x0000

10.02.2015 20:45:24: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:24: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:24: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:24: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:24: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:24: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:24: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:24: NibeRS485: Received:

5C 00 29 90 00 B9

10.02.2015 20:45:24: NibeRS485: Ignoring

10.02.2015 20:45:25: NibeRS485: Received:

5C 00 29 55 02 08 00 76

10.02.2015 20:45:25: NibeRS485: Ignoring

10.02.2015 20:45:25: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:45:25: NibeRS485: Sending ACK

10.02.2015 20:45:25: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:25: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:45:25: NibeRS485: Sending ACK

10.02.2015 20:45:25: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:25: NibeRS485: Received:

5C 00 29 90 00 B9

10.02.2015 20:45:25: NibeRS485: Ignoring

10.02.2015 20:45:25: NibeRS485: Running nibeBus query with id 40004

10.02.2015 20:45:25: NibeRS485: No data found with id 40004

10.02.2015 20:45:26: NibeRS485: Received:

5C 00 29 55 02 08 00 76

10.02.2015 20:45:26: NibeRS485: Ignoring

10.02.2015 20:45:26: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:45:26: NibeRS485: Sending ACK

10.02.2015 20:45:26: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:26: NibeRS485: Running nibeBus query with id 40004

10.02.2015 20:45:26: NibeRS485: No data found with id 40004
10.02.2015 20:45:26: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:26: NibeRS485: Sending ACK
10.02.2015 20:45:26: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:26: NibeRS485: Received:
5C 00 20 68 50 93 9C 3D 00 94 9C 00 00 91 9C 14
00 92 9C 00 00 8F 9C 0A 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 20

10.02.2015 20:45:26: NibeRS485: Sending ACK
10.02.2015 20:45:26: NibeRS485: Got data for id 40083: 0x003D
10.02.2015 20:45:26: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:26: NibeRS485: Got data for id 40081: 0x0014
10.02.2015 20:45:26: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:26: NibeRS485: Got data for id 40079: 0x000A
10.02.2015 20:45:26: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:26: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:26: NibeRS485: Ignoring
10.02.2015 20:45:27: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:27: NibeRS485: Ignoring
10.02.2015 20:45:27: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:45:27: NibeRS485: Sending ACK
10.02.2015 20:45:27: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:45:27: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:27: NibeRS485: Sending ACK
10.02.2015 20:45:27: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:27: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:27: NibeRS485: Sending ACK
10.02.2015 20:45:27: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:27: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:27: NibeRS485: Ignoring
10.02.2015 20:45:27: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:27: NibeRS485: No data found with id 40004
10.02.2015 20:45:28: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:28: TaloLoggerThreadStore: Logged data for timestamp 20150210204525
dummy: 11.9

nibeoutdoor: 3.0
10.02.2015 20:45:28: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:28: NibeRS485: Ignoring
10.02.2015 20:45:28: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:28: NibeRS485: Sending ACK
10.02.2015 20:45:28: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:28: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:28: NibeRS485: Sending ACK
10.02.2015 20:45:28: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:28: NibeRS485: Received:
5C 00 20 68 50 93 9C 30 00 94 9C 00 00 91 9C 17
00 92 9C 00 00 8F 9C 0A 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2E

10.02.2015 20:45:28: NibeRS485: Sending ACK
10.02.2015 20:45:28: NibeRS485: Got data for id 40083: 0x0030
10.02.2015 20:45:28: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 40081: 0x0017
10.02.2015 20:45:28: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 40079: 0x000A
10.02.2015 20:45:28: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:28: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:28: NibeRS485: Ignoring
10.02.2015 20:45:29: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:29: NibeRS485: Ignoring
10.02.2015 20:45:29: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:29: NibeRS485: Sending ACK
10.02.2015 20:45:29: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:29: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:29: NibeRS485: Sending ACK
10.02.2015 20:45:29: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:29: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:29: NibeRS485: Ignoring
10.02.2015 20:45:30: NibeRS485: Received:

5C 00 29 55 02 08 00 76

10.02.2015 20:45:30: NibeRS485: Ignoring

10.02.2015 20:45:30: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:45:30: NibeRS485: Sending ACK

10.02.2015 20:45:30: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:30: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:45:30: NibeRS485: Sending ACK

10.02.2015 20:45:30: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:30: NibeRS485: Received:

5C 00 20 68 50 93 9C 30 00 94 9C 00 00 91 9C 17
00 92 9C 00 00 8F 9C 0A 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2E

10.02.2015 20:45:30: NibeRS485: Sending ACK

10.02.2015 20:45:30: NibeRS485: Got data for id 40083: 0x0030

10.02.2015 20:45:30: NibeRS485: Got data for id 40084: 0x0000

10.02.2015 20:45:30: NibeRS485: Got data for id 40081: 0x0017

10.02.2015 20:45:30: NibeRS485: Got data for id 40082: 0x0000

10.02.2015 20:45:30: NibeRS485: Got data for id 40079: 0x000A

10.02.2015 20:45:30: NibeRS485: Got data for id 40080: 0x0000

10.02.2015 20:45:30: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:30: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:30: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:30: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:30: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:30: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:30: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:30: NibeRS485: Received:

5C 00 29 90 00 B9

10.02.2015 20:45:30: NibeRS485: Ignoring

10.02.2015 20:45:30: NibeRS485: Running nibeBus query with id 40004

10.02.2015 20:45:30: NibeRS485: No data found with id 40004

10.02.2015 20:45:31: NibeRS485: Received:

5C 00 29 55 02 08 00 76

10.02.2015 20:45:31: NibeRS485: Ignoring

10.02.2015 20:45:31: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:45:31: NibeRS485: Sending ACK

10.02.2015 20:45:31: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:31: NibeRS485: Running nibeBus query with id 40004

10.02.2015 20:45:31: NibeRS485: No data found with id 40004

10.02.2015 20:45:31: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:45:31: NibeRS485: Sending ACK

10.02.2015 20:45:31: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:31: NibeRS485: Received:

5C 00 29 90 00 B9

10.02.2015 20:45:31: NibeRS485: Ignoring
10.02.2015 20:45:32: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:32: NibeRS485: Ignoring
10.02.2015 20:45:32: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:45:32: NibeRS485: Sending ACK
10.02.2015 20:45:32: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:45:32: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:32: NibeRS485: Sending ACK
10.02.2015 20:45:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:32: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:32: NibeRS485: Sending ACK
10.02.2015 20:45:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:32: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:32: NibeRS485: No data found with id 40004
10.02.2015 20:45:32: NibeRS485: Received:
5C 00 20 68 50 93 9C 28 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 35

10.02.2015 20:45:32: NibeRS485: Sending ACK
10.02.2015 20:45:32: NibeRS485: Got data for id 40083: 0x0028
10.02.2015 20:45:32: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:32: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:45:32: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:32: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:45:32: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:32: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:32: NibeRS485: Ignoring
10.02.2015 20:45:32: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:32: NibeRS485: Sending ACK
10.02.2015 20:45:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:32: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:32: NibeRS485: Sending ACK
10.02.2015 20:45:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:33: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:33: TaloLoggerThreadStore: Logged data for timestamp 20150210204530

dummy: 11.9
nibeoutdoor: 3.0
10.02.2015 20:45:33: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:33: NibeRS485: Ignoring
10.02.2015 20:45:33: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:33: NibeRS485: Sending ACK
10.02.2015 20:45:33: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:33: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:33: NibeRS485: Sending ACK
10.02.2015 20:45:33: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:33: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:33: NibeRS485: Ignoring
10.02.2015 20:45:34: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:34: NibeRS485: Ignoring
10.02.2015 20:45:34: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:34: NibeRS485: Sending ACK
10.02.2015 20:45:34: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:34: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:34: NibeRS485: Sending ACK
10.02.2015 20:45:34: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:34: NibeRS485: Received:
5C 00 20 68 50 93 9C 27 00 94 9C 00 00 91 9C 15
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 38

10.02.2015 20:45:34: NibeRS485: Sending ACK
10.02.2015 20:45:34: NibeRS485: Got data for id 40083: 0x0027
10.02.2015 20:45:34: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:34: NibeRS485: Got data for id 40081: 0x0015
10.02.2015 20:45:34: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:34: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:45:34: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:34: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:34: NibeRS485: Ignoring

```
10.02.2015 20:45:35: NibeRS485: Received:
5C 00 29 55 02 08 00 76
```

10.02.2015 20:45:36: NibeRS485: Ignoring
10.02.2015 20:45:37: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:37: NibeRS485: Ignoring
10.02.2015 20:45:37: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:45:37: NibeRS485: Sending ACK
10.02.2015 20:45:37: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:45:37: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:37: NibeRS485: Sending ACK
10.02.2015 20:45:37: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:37: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:37: NibeRS485: Sending ACK
10.02.2015 20:45:37: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:37: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:45:37: NibeRS485: Sending ACK
10.02.2015 20:45:37: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:37: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:37: NibeRS485: Ignoring
10.02.2015 20:45:37: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:37: NibeRS485: No data found with id 40004
10.02.2015 20:45:38: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:38: TaloLoggerThreadStore: Logged data for timestamp 20150210204535
dummy: 11.8
nibeoutdoor: 3.0

10.02.2015 20:45:38: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:38: NibeRS485: Ignoring
10.02.2015 20:45:38: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:38: NibeRS485: Sending ACK
10.02.2015 20:45:38: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:38: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:38: NibeRS485: Sending ACK
10.02.2015 20:45:38: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:38: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:38: NibeRS485: Ignoring
10.02.2015 20:45:39: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:39: NibeRS485: Ignoring
10.02.2015 20:45:39: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:45:39: NibeRS485: Sending ACK
10.02.2015 20:45:39: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:39: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:39: NibeRS485: Sending ACK
10.02.2015 20:45:39: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:39: NibeRS485: Received:
5C 00 20 68 50 93 9C 2E 00 94 9C 00 00 91 9C 17
00 92 9C 00 00 8F 9C 0B 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 31

10.02.2015 20:45:39: NibeRS485: Sending ACK
10.02.2015 20:45:39: NibeRS485: Got data for id 40083: 0x002E
10.02.2015 20:45:39: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:39: NibeRS485: Got data for id 40081: 0x0017
10.02.2015 20:45:39: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:39: NibeRS485: Got data for id 40079: 0x000B
10.02.2015 20:45:39: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:39: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:39: NibeRS485: Ignoring
10.02.2015 20:45:40: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:40: NibeRS485: Ignoring
10.02.2015 20:45:40: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:40: NibeRS485: Sending ACK
10.02.2015 20:45:40: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:40: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:40: NibeRS485: Sending ACK
10.02.2015 20:45:40: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:40: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:40: NibeRS485: Ignoring
10.02.2015 20:45:40: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:40: NibeRS485: No data found with id 40004
10.02.2015 20:45:41: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:41: NibeRS485: Ignoring
10.02.2015 20:45:41: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:45:41: NibeRS485: Sending ACK
10.02.2015 20:45:41: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:41: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:41: NibeRS485: No data found with id 40004
10.02.2015 20:45:41: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:41: NibeRS485: Sending ACK
10.02.2015 20:45:41: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:41: NibeRS485: Received:
5C 00 20 68 50 93 9C 33 00 94 9C 00 00 91 9C 1A
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 23

10.02.2015 20:45:41: NibeRS485: Sending ACK
10.02.2015 20:45:41: NibeRS485: Got data for id 40083: 0x0033
10.02.2015 20:45:41: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:41: NibeRS485: Got data for id 40081: 0x001A
10.02.2015 20:45:41: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:41: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:45:41: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:41: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:41: NibeRS485: Ignoring
10.02.2015 20:45:42: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:42: NibeRS485: Ignoring
10.02.2015 20:45:42: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1F 00 00 00 8B

10.02.2015 20:45:42: NibeRS485: Sending ACK
10.02.2015 20:45:42: NibeRS485: Got queried data for id 40004: 0x001F
10.02.2015 20:45:42: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:42: NibeRS485: Sending ACK
10.02.2015 20:45:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:42: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:42: NibeRS485: Sending ACK
10.02.2015 20:45:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:42: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:42: NibeRS485: Ignoring

10.02.2015 20:45:42: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:42: NibeRS485: Sending ACK
10.02.2015 20:45:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:42: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:42: NibeRS485: No data found with id 40004
10.02.2015 20:45:42: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:42: NibeRS485: Sending ACK
10.02.2015 20:45:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:43: TalLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:43: TalLoggerThreadStore: Logged data for timestamp 20150210204540
dummy: 11.8
nibeoutdoor: 3.1

10.02.2015 20:45:43: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:43: NibeRS485: Ignoring
10.02.2015 20:45:43: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:43: NibeRS485: Sending ACK
10.02.2015 20:45:43: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:43: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:43: NibeRS485: Sending ACK
10.02.2015 20:45:43: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:43: NibeRS485: Received:
5C 00 20 68 50 93 9C 34 00 94 9C 00 00 91 9C 1A
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 24

10.02.2015 20:45:43: NibeRS485: Sending ACK
10.02.2015 20:45:43: NibeRS485: Got data for id 40083: 0x0034
10.02.2015 20:45:43: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:43: NibeRS485: Got data for id 40081: 0x001A
10.02.2015 20:45:43: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:43: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:45:43: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:43: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:43: NibeRS485: Ignoring
10.02.2015 20:45:44: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:44: NibeRS485: Ignoring

10.02.2015 20:45:44: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:44: NibeRS485: Sending ACK
10.02.2015 20:45:44: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:44: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:44: NibeRS485: Sending ACK
10.02.2015 20:45:44: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:44: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:44: NibeRS485: Ignoring
10.02.2015 20:45:45: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:45: NibeRS485: Ignoring
10.02.2015 20:45:45: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:45: NibeRS485: Sending ACK
10.02.2015 20:45:45: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:45: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:45: NibeRS485: Sending ACK
10.02.2015 20:45:45: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:45: NibeRS485: Received:
5C 00 20 68 50 93 9C 22 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 3E

10.02.2015 20:45:45: NibeRS485: Sending ACK
10.02.2015 20:45:45: NibeRS485: Got data for id 40083: 0x0022
10.02.2015 20:45:45: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:45: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:45:45: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:45: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:45:45: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:45: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:45: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:45: NibeRS485: Ignoring
10.02.2015 20:45:45: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:45: NibeRS485: No data found with id 40004
10.02.2015 20:45:46: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:46: NibeRS485: Ignoring

```
10.02.2015 20:45:46: NibeRS485: Received:
5C 00 20 6B 00 4B
```

5C 00 29 90 00 B9

10.02.2015 20:45:47: NibeRS485: Ignoring

10.02.2015 20:45:48: TalLoggerThreadStore: Storing logged data with 2 points.

10.02.2015 20:45:48: TalLoggerThreadStore: Logged data for timestamp 20150210204545

dummy: 11.8

nibeoutdoor: 3.0

10.02.2015 20:45:48: NibeRS485: Received:

5C 00 29 55 02 08 00 76

10.02.2015 20:45:48: NibeRS485: Ignoring

10.02.2015 20:45:48: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:45:48: NibeRS485: Sending ACK

10.02.2015 20:45:48: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:48: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:45:48: NibeRS485: Sending ACK

10.02.2015 20:45:48: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:48: NibeRS485: Received:

5C 00 29 90 00 B9

10.02.2015 20:45:48: NibeRS485: Ignoring

10.02.2015 20:45:49: NibeRS485: Received:

5C 00 29 55 02 08 00 76

10.02.2015 20:45:49: NibeRS485: Ignoring

10.02.2015 20:45:49: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:45:49: NibeRS485: Sending ACK

10.02.2015 20:45:49: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:49: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:45:49: NibeRS485: Sending ACK

10.02.2015 20:45:49: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:45:49: NibeRS485: Received:

5C 00 20 68 50 93 9C 23 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0A 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 39

10.02.2015 20:45:49: NibeRS485: Sending ACK

10.02.2015 20:45:49: NibeRS485: Got data for id 40083: 0x0023

10.02.2015 20:45:49: NibeRS485: Got data for id 40084: 0x0000

10.02.2015 20:45:49: NibeRS485: Got data for id 40081: 0x0013

10.02.2015 20:45:49: NibeRS485: Got data for id 40082: 0x0000

10.02.2015 20:45:49: NibeRS485: Got data for id 40079: 0x000A

10.02.2015 20:45:49: NibeRS485: Got data for id 40080: 0x0000

10.02.2015 20:45:49: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:49: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:49: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:49: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:49: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:49: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:49: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:49: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:49: NibeRS485: Ignoring
10.02.2015 20:45:50: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:50: NibeRS485: Ignoring
10.02.2015 20:45:50: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:50: NibeRS485: Sending ACK
10.02.2015 20:45:50: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:50: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:50: NibeRS485: Sending ACK
10.02.2015 20:45:50: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:50: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:50: NibeRS485: Ignoring
10.02.2015 20:45:50: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:50: NibeRS485: No data found with id 40004
10.02.2015 20:45:51: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:51: NibeRS485: Ignoring
10.02.2015 20:45:51: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:51: NibeRS485: Sending ACK
10.02.2015 20:45:51: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:51: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:51: NibeRS485: No data found with id 40004
10.02.2015 20:45:51: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:51: NibeRS485: Sending ACK
10.02.2015 20:45:51: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:51: NibeRS485: Received:
5C 00 20 68 50 93 9C 23 00 94 9C 00 00 91 9C 18
00 92 9C 00 00 8F 9C 08 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 30

10.02.2015 20:45:51: NibeRS485: Sending ACK
10.02.2015 20:45:51: NibeRS485: Got data for id 40083: 0x0023
10.02.2015 20:45:51: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:51: NibeRS485: Got data for id 40081: 0x0018
10.02.2015 20:45:51: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:51: NibeRS485: Got data for id 40079: 0x0008
10.02.2015 20:45:51: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:51: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:45:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:51: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:51: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:51: NibeRS485: Ignoring
10.02.2015 20:45:52: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:52: NibeRS485: Ignoring
10.02.2015 20:45:52: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:45:52: NibeRS485: Sending ACK
10.02.2015 20:45:52: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:45:52: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:52: NibeRS485: No data found with id 40004
10.02.2015 20:45:52: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:52: NibeRS485: Sending ACK
10.02.2015 20:45:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:52: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:52: NibeRS485: Sending ACK
10.02.2015 20:45:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:52: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:45:52: NibeRS485: Sending ACK
10.02.2015 20:45:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:52: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:52: NibeRS485: Ignoring
10.02.2015 20:45:52: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:52: NibeRS485: Sending ACK
10.02.2015 20:45:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:52: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:45:52: NibeRS485: Sending ACK
10.02.2015 20:45:52: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:53: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:45:53: TaloLoggerThreadStore: Logged data for timestamp 20150210204550
dummy: 11.8
nibeoutdoor: 3.0
10.02.2015 20:45:53: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:53: NibeRS485: Ignoring
10.02.2015 20:45:53: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:53: NibeRS485: Sending ACK

10.02.2015 20:45:53: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:53: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:53: NibeRS485: Sending ACK
10.02.2015 20:45:53: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:53: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:53: NibeRS485: Ignoring
10.02.2015 20:45:54: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:54: NibeRS485: Ignoring
10.02.2015 20:45:54: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:54: NibeRS485: Sending ACK
10.02.2015 20:45:54: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:54: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:54: NibeRS485: Sending ACK
10.02.2015 20:45:54: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:54: NibeRS485: Received:
5C 00 20 68 50 93 9C 2A 00 94 9C 00 00 91 9C 14
00 92 9C 00 00 8F 9C 0A 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 37

10.02.2015 20:45:54: NibeRS485: Sending ACK
10.02.2015 20:45:54: NibeRS485: Got data for id 40083: 0x002A
10.02.2015 20:45:54: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:54: NibeRS485: Got data for id 40081: 0x0014
10.02.2015 20:45:54: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:54: NibeRS485: Got data for id 40079: 0x000A
10.02.2015 20:45:54: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:54: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:54: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:54: NibeRS485: Ignoring
10.02.2015 20:45:55: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:55: NibeRS485: Ignoring
10.02.2015 20:45:55: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:55: NibeRS485: Sending ACK
10.02.2015 20:45:55: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:55: NibeRS485: Received:

5C 00 20 69 00 49

10.02.2015 20:45:55: NibeRS485: Sending ACK
10.02.2015 20:45:55: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:55: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:55: NibeRS485: Ignoring
10.02.2015 20:45:55: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:55: NibeRS485: No data found with id 40004
10.02.2015 20:45:56: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:56: NibeRS485: Ignoring
10.02.2015 20:45:56: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:56: NibeRS485: Sending ACK
10.02.2015 20:45:56: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:56: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:45:56: NibeRS485: No data found with id 40004
10.02.2015 20:45:56: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:56: NibeRS485: Sending ACK
10.02.2015 20:45:56: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:56: NibeRS485: Received:
5C 00 20 68 50 93 9C 33 00 94 9C 00 00 91 9C 1A
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 23

10.02.2015 20:45:56: NibeRS485: Sending ACK
10.02.2015 20:45:56: NibeRS485: Got data for id 40083: 0x0033
10.02.2015 20:45:56: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:45:56: NibeRS485: Got data for id 40081: 0x001A
10.02.2015 20:45:56: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:45:56: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:45:56: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:45:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:56: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:45:56: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:56: NibeRS485: Ignoring
10.02.2015 20:45:57: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:57: NibeRS485: Ignoring
10.02.2015 20:45:57: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:45:57: NibeRS485: Sending ACK

[illegible]

10.02.2015 20:45:58: NibeRS485: Ignoring
10.02.2015 20:45:59: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:45:59: NibeRS485: Ignoring
10.02.2015 20:45:59: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:45:59: NibeRS485: Sending ACK
10.02.2015 20:45:59: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:59: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:45:59: NibeRS485: Sending ACK
10.02.2015 20:45:59: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:45:59: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:45:59: NibeRS485: Ignoring
10.02.2015 20:46:00: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:00: NibeRS485: Ignoring
10.02.2015 20:46:00: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:00: NibeRS485: Sending ACK
10.02.2015 20:46:00: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:00: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:00: NibeRS485: Sending ACK
10.02.2015 20:46:00: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:00: NibeRS485: Received:
5C 00 20 68 50 93 9C 27 00 94 9C 00 00 91 9C 11
00 92 9C 00 00 8F 9C 0B 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 3E

10.02.2015 20:46:00: NibeRS485: Sending ACK
10.02.2015 20:46:00: NibeRS485: Got data for id 40083: 0x0027
10.02.2015 20:46:00: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:00: NibeRS485: Got data for id 40081: 0x0011
10.02.2015 20:46:00: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:00: NibeRS485: Got data for id 40079: 0x000B
10.02.2015 20:46:00: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:00: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:00: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:00: NibeRS485: Ignoring
10.02.2015 20:46:00: NibeRS485: Running nibeBus query with id 40004

10.02.2015 20:46:00: NibeRS485: No data found with id 40004
10.02.2015 20:46:01: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:01: NibeRS485: Ignoring
10.02.2015 20:46:01: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:01: NibeRS485: Sending ACK
10.02.2015 20:46:01: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:01: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:01: NibeRS485: No data found with id 40004
10.02.2015 20:46:01: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:01: NibeRS485: Sending ACK
10.02.2015 20:46:01: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:01: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:01: NibeRS485: Ignoring
10.02.2015 20:46:02: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:02: NibeRS485: Ignoring
10.02.2015 20:46:02: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1F 00 00 00 8B

10.02.2015 20:46:02: NibeRS485: Sending ACK
10.02.2015 20:46:02: NibeRS485: Got queried data for id 40004: 0x001F
10.02.2015 20:46:02: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:02: NibeRS485: Sending ACK
10.02.2015 20:46:02: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:02: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:02: NibeRS485: No data found with id 40004
10.02.2015 20:46:02: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:02: NibeRS485: Sending ACK
10.02.2015 20:46:02: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:02: NibeRS485: Received:
5C 00 20 68 50 93 9C 2B 00 94 9C 00 00 91 9C 18
00 92 9C 00 00 8F 9C 08 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 38

10.02.2015 20:46:02: NibeRS485: Sending ACK
10.02.2015 20:46:02: NibeRS485: Got data for id 40083: 0x002B
10.02.2015 20:46:02: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:02: NibeRS485: Got data for id 40081: 0x0018
10.02.2015 20:46:02: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:02: NibeRS485: Got data for id 40079: 0x0008
10.02.2015 20:46:02: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:02: NibeRS485: Got data for id 65535: 0x0000

10.02.2015 20:46:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:02: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:02: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:02: NibeRS485: Ignoring
10.02.2015 20:46:02: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:02: NibeRS485: Sending ACK
10.02.2015 20:46:02: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:02: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:02: NibeRS485: Sending ACK
10.02.2015 20:46:02: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:03: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:46:03: TaloLoggerThreadStore: Logged data for timestamp 20150210204600
dummy: 11.7
nibeoutdoor: 3.1
10.02.2015 20:46:03: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:03: NibeRS485: Ignoring
10.02.2015 20:46:03: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:03: NibeRS485: Sending ACK
10.02.2015 20:46:03: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:03: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:03: NibeRS485: Sending ACK
10.02.2015 20:46:03: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:03: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:03: NibeRS485: Ignoring
10.02.2015 20:46:04: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:04: NibeRS485: Ignoring
10.02.2015 20:46:04: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:04: NibeRS485: Sending ACK
10.02.2015 20:46:04: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:04: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:04: NibeRS485: Sending ACK
10.02.2015 20:46:04: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:04: NibeRS485: Received:
5C 00 20 68 50 93 9C 25 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 00 8F 9C 0D 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 38

10.02.2015 20:46:04: NibeRS485: Sending ACK
10.02.2015 20:46:04: NibeRS485: Got data for id 40083: 0x0025
10.02.2015 20:46:04: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:04: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:46:04: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:04: NibeRS485: Got data for id 40079: 0x000D
10.02.2015 20:46:04: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:04: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:04: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:04: NibeRS485: Ignoring
10.02.2015 20:46:05: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:05: NibeRS485: Ignoring
10.02.2015 20:46:05: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:05: NibeRS485: Sending ACK
10.02.2015 20:46:05: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:05: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:05: NibeRS485: Sending ACK
10.02.2015 20:46:05: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:05: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:05: NibeRS485: Ignoring
10.02.2015 20:46:05: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:05: NibeRS485: No data found with id 40004
10.02.2015 20:46:06: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:06: NibeRS485: Ignoring
10.02.2015 20:46:06: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:06: NibeRS485: Sending ACK
10.02.2015 20:46:06: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:06: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:06: NibeRS485: No data found with id 40004
10.02.2015 20:46:06: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:06: NibeRS485: Sending ACK
10.02.2015 20:46:06: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:06: NibeRS485: Received:
5C 00 20 68 50 93 9C 28 00 94 9C 00 00 91 9C 15
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 37

10.02.2015 20:46:06: NibeRS485: Sending ACK
10.02.2015 20:46:06: NibeRS485: Got data for id 40083: 0x0028
10.02.2015 20:46:06: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:06: NibeRS485: Got data for id 40081: 0x0015
10.02.2015 20:46:06: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:06: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:46:06: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:06: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:06: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:06: NibeRS485: Ignoring
10.02.2015 20:46:07: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:07: NibeRS485: Ignoring
10.02.2015 20:46:07: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1F 00 00 00 8B

10.02.2015 20:46:07: NibeRS485: Sending ACK
10.02.2015 20:46:07: NibeRS485: Got queried data for id 40004: 0x001F
10.02.2015 20:46:07: NibeRS485: Received:
5C 00 20 6B 00 4B
10.02.2015 20:46:07: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:07: NibeRS485: No data found with id 40004

10.02.2015 20:46:07: NibeRS485: Sending ACK
10.02.2015 20:46:07: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:07: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:07: NibeRS485: Sending ACK
10.02.2015 20:46:07: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:07: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:46:07: NibeRS485: Sending ACK
10.02.2015 20:46:07: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:07: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:07: NibeRS485: Ignoring
10.02.2015 20:46:08: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:46:08: TaloLoggerThreadStore: Logged data for timestamp 20150210204605
dummy: 11.7
nibeoutdoor: 3.1
10.02.2015 20:46:08: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:08: NibeRS485: Ignoring
10.02.2015 20:46:08: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:08: NibeRS485: Sending ACK
10.02.2015 20:46:08: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:08: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:08: NibeRS485: Sending ACK
10.02.2015 20:46:08: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:08: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:08: NibeRS485: Ignoring
10.02.2015 20:46:09: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:09: NibeRS485: Ignoring
10.02.2015 20:46:09: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:09: NibeRS485: Sending ACK
10.02.2015 20:46:09: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:09: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:09: NibeRS485: Sending ACK
10.02.2015 20:46:09: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:09: NibeRS485: Received:
5C 00 20 68 50 93 9C 2F 00 94 9C 00 00 91 9C 19
00 92 9C 00 00 8F 9C 08 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 3D

10.02.2015 20:46:09: NibeRS485: Sending ACK
10.02.2015 20:46:09: NibeRS485: Got data for id 40083: 0x002F
10.02.2015 20:46:09: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:09: NibeRS485: Got data for id 40081: 0x0019
10.02.2015 20:46:09: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:09: NibeRS485: Got data for id 40079: 0x0008
10.02.2015 20:46:09: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:09: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:09: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:09: NibeRS485: Ignoring
10.02.2015 20:46:10: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:10: NibeRS485: Ignoring
10.02.2015 20:46:10: NibeRS485: Received:

5C 00 20 6B 00 4B

10.02.2015 20:46:10: NibeRS485: Sending ACK
10.02.2015 20:46:10: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:10: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:10: NibeRS485: Sending ACK
10.02.2015 20:46:10: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:10: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:10: NibeRS485: Ignoring
10.02.2015 20:46:10: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:10: NibeRS485: No data found with id 40004
10.02.2015 20:46:11: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:11: NibeRS485: Ignoring
10.02.2015 20:46:11: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:11: NibeRS485: Sending ACK
10.02.2015 20:46:11: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:11: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:11: NibeRS485: No data found with id 40004
10.02.2015 20:46:11: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:11: NibeRS485: Sending ACK
10.02.2015 20:46:11: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:11: NibeRS485: Received:
5C 00 20 68 50 93 9C 35 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 29

10.02.2015 20:46:11: NibeRS485: Sending ACK
10.02.2015 20:46:11: NibeRS485: Got data for id 40083: 0x0035
10.02.2015 20:46:11: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:11: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:46:11: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:11: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:46:11: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:11: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:11: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:11: NibeRS485: Ignoring
10.02.2015 20:46:12: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:12: NibeRS485: Ignoring
10.02.2015 20:46:12: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1F 00 00 00 8B

10.02.2015 20:46:12: NibeRS485: Sending ACK
10.02.2015 20:46:12: NibeRS485: Got queried data for id 40004: 0x001F
10.02.2015 20:46:12: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:12: NibeRS485: Sending ACK
10.02.2015 20:46:12: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:12: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:12: NibeRS485: No data found with id 40004
10.02.2015 20:46:12: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:12: NibeRS485: Sending ACK
10.02.2015 20:46:12: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:12: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:12: NibeRS485: Ignoring
10.02.2015 20:46:12: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:12: NibeRS485: Sending ACK
10.02.2015 20:46:12: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:12: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:12: NibeRS485: Sending ACK
10.02.2015 20:46:12: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:13: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:46:13: TaloLoggerThreadStore: Logged data for timestamp 20150210204610
dummy: 11.6
nibeoutdoor: 3.1
10.02.2015 20:46:13: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:13: NibeRS485: Ignoring
10.02.2015 20:46:13: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:13: NibeRS485: Sending ACK
10.02.2015 20:46:13: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:13: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:13: NibeRS485: Sending ACK
10.02.2015 20:46:13: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:13: NibeRS485: Received:
5C 00 20 68 50 93 9C 34 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0D 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 29

10.02.2015 20:46:13: NibeRS485: Sending ACK
10.02.2015 20:46:13: NibeRS485: Got data for id 40083: 0x0034

10.02.2015 20:46:13: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:13: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:46:13: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:13: NibeRS485: Got data for id 40079: 0x0000
10.02.2015 20:46:13: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:13: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:13: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:13: NibeRS485: Ignoring
10.02.2015 20:46:14: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:14: NibeRS485: Ignoring
10.02.2015 20:46:14: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:14: NibeRS485: Sending ACK
10.02.2015 20:46:14: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:14: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:14: NibeRS485: Sending ACK
10.02.2015 20:46:14: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:14: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:14: NibeRS485: Ignoring
10.02.2015 20:46:15: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:15: NibeRS485: Ignoring
10.02.2015 20:46:15: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:15: NibeRS485: Sending ACK
10.02.2015 20:46:15: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:15: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:15: NibeRS485: Sending ACK
10.02.2015 20:46:15: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:15: NibeRS485: Received:
5C 00 20 68 50 93 9C 48 00 94 9C 00 00 91 9C 1A
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 58

10.02.2015 20:46:15: NibeRS485: Sending ACK
10.02.2015 20:46:15: NibeRS485: Got data for id 40083: 0x0048
10.02.2015 20:46:15: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:15: NibeRS485: Got data for id 40081: 0x001A

10.02.2015 20:46:15: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:15: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:46:15: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:15: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:15: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:15: NibeRS485: Ignoring
10.02.2015 20:46:15: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:15: NibeRS485: No data found with id 40004
10.02.2015 20:46:16: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:16: NibeRS485: Ignoring
10.02.2015 20:46:16: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:16: NibeRS485: Sending ACK
10.02.2015 20:46:16: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:16: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:16: NibeRS485: No data found with id 40004
10.02.2015 20:46:16: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:16: NibeRS485: Sending ACK
10.02.2015 20:46:16: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:16: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:16: NibeRS485: Ignoring
10.02.2015 20:46:17: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:17: NibeRS485: Sending ACK
10.02.2015 20:46:17: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:17: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:17: NibeRS485: No data found with id 40004
10.02.2015 20:46:17: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:17: NibeRS485: Sending ACK
10.02.2015 20:46:17: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:17: NibeRS485: Received:
5C 00 20 68 50 93 9C 37 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2A

10.02.2015 20:46:17: NibeRS485: Sending ACK
10.02.2015 20:46:17: NibeRS485: Got data for id 40083: 0x0037
10.02.2015 20:46:17: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:17: NibeRS485: Got data for id 40081: 0x0012

10.02.2015 20:46:17: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:17: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:46:17: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:17: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:17: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:17: NibeRS485: Ignoring
10.02.2015 20:46:17: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:17: NibeRS485: Ignoring
10.02.2015 20:46:17: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:46:17: NibeRS485: Sending ACK
10.02.2015 20:46:17: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:46:17: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:17: NibeRS485: No data found with id 40004
10.02.2015 20:46:18: TalLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:46:18: TalLoggerThreadStore: Logged data for timestamp 20150210204615
dummy: 11.6
nibeoutdoor: 3.0
10.02.2015 20:46:18: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:18: NibeRS485: Ignoring
10.02.2015 20:46:18: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:46:18: NibeRS485: Sending ACK
10.02.2015 20:46:18: NibeRS485: ERROR: Received unqueried or cancelled query data with 0x6A frame.
10.02.2015 20:46:18: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:18: NibeRS485: Sending ACK
10.02.2015 20:46:18: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:18: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:18: NibeRS485: Sending ACK
10.02.2015 20:46:18: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:18: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:18: NibeRS485: Ignoring
10.02.2015 20:46:19: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:19: NibeRS485: Ignoring
10.02.2015 20:46:19: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:19: NibeRS485: Sending ACK
10.02.2015 20:46:19: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:19: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:19: NibeRS485: Sending ACK
10.02.2015 20:46:19: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:19: NibeRS485: Received:
5C 00 20 68 50 93 9C 38 00 94 9C 00 00 91 9C 16
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 24

10.02.2015 20:46:19: NibeRS485: Sending ACK
10.02.2015 20:46:19: NibeRS485: Got data for id 40083: 0x0038
10.02.2015 20:46:19: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:19: NibeRS485: Got data for id 40081: 0x0016
10.02.2015 20:46:19: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:19: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:46:19: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:19: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:19: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:19: NibeRS485: Ignoring
10.02.2015 20:46:20: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:20: NibeRS485: Ignoring
10.02.2015 20:46:20: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:20: NibeRS485: Sending ACK
10.02.2015 20:46:20: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:20: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:20: NibeRS485: Sending ACK
10.02.2015 20:46:20: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:20: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:20: NibeRS485: Ignoring
10.02.2015 20:46:20: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:20: NibeRS485: No data found with id 40004
10.02.2015 20:46:21: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:21: NibeRS485: Ignoring
10.02.2015 20:46:21: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:21: NibeRS485: Sending ACK
10.02.2015 20:46:21: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:21: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:21: NibeRS485: No data found with id 40004
10.02.2015 20:46:21: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:21: NibeRS485: Sending ACK
10.02.2015 20:46:21: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:21: NibeRS485: Received:
5C 00 20 68 50 93 9C 35 00 94 9C 00 00 91 9C 11
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2E

10.02.2015 20:46:21: NibeRS485: Sending ACK
10.02.2015 20:46:21: NibeRS485: Got data for id 40083: 0x0035
10.02.2015 20:46:21: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:21: NibeRS485: Got data for id 40081: 0x0011
10.02.2015 20:46:21: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:21: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:46:21: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:21: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:21: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:21: NibeRS485: Ignoring
10.02.2015 20:46:22: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:22: NibeRS485: Ignoring
10.02.2015 20:46:22: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:46:22: NibeRS485: Sending ACK
10.02.2015 20:46:22: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:46:22: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:22: NibeRS485: Sending ACK
10.02.2015 20:46:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:22: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:22: NibeRS485: Sending ACK
10.02.2015 20:46:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:22: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:22: NibeRS485: No data found with id 40004
10.02.2015 20:46:22: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:46:22: NibeRS485: Sending ACK
10.02.2015 20:46:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:22: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:22: NibeRS485: Ignoring
10.02.2015 20:46:22: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:22: NibeRS485: Sending ACK
10.02.2015 20:46:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:22: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:22: NibeRS485: Sending ACK
10.02.2015 20:46:22: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:23: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:46:23: TaloLoggerThreadStore: Logged data for timestamp 20150210204620
dummy: 11.6
nibeoutdoor: 3.0
10.02.2015 20:46:23: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:23: NibeRS485: Ignoring
10.02.2015 20:46:23: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:23: NibeRS485: Sending ACK
10.02.2015 20:46:23: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:23: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:23: NibeRS485: Sending ACK
10.02.2015 20:46:23: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:23: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:23: NibeRS485: Ignoring
10.02.2015 20:46:24: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:24: NibeRS485: Ignoring
10.02.2015 20:46:24: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:24: NibeRS485: Sending ACK
10.02.2015 20:46:24: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:24: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:24: NibeRS485: Sending ACK
10.02.2015 20:46:24: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:24: NibeRS485: Received:
5C 00 20 68 50 93 9C 27 00 94 9C 00 00 91 9C 18
00 92 9C 00 00 8F 9C 08 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 34

10.02.2015 20:46:24: NibeRS485: Sending ACK
10.02.2015 20:46:24: NibeRS485: Got data for id 40083: 0x0027
10.02.2015 20:46:24: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:24: NibeRS485: Got data for id 40081: 0x0018
10.02.2015 20:46:24: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:24: NibeRS485: Got data for id 40079: 0x0008
10.02.2015 20:46:24: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:24: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:24: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:24: NibeRS485: Ignoring
10.02.2015 20:46:25: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:25: NibeRS485: Ignoring
10.02.2015 20:46:25: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:25: NibeRS485: Sending ACK
10.02.2015 20:46:25: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:25: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:25: NibeRS485: Sending ACK
10.02.2015 20:46:25: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:25: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:25: NibeRS485: Ignoring
10.02.2015 20:46:25: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:25: NibeRS485: No data found with id 40004
10.02.2015 20:46:26: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:26: NibeRS485: Ignoring
10.02.2015 20:46:26: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:26: NibeRS485: Sending ACK
10.02.2015 20:46:26: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:26: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:26: NibeRS485: No data found with id 40004
10.02.2015 20:46:26: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:26: NibeRS485: Sending ACK
10.02.2015 20:46:26: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:26: NibeRS485: Received:
5C 00 20 68 50 93 9C 24 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 38

10.02.2015 20:46:26: NibeRS485: Sending ACK
10.02.2015 20:46:26: NibeRS485: Got data for id 40083: 0x0024
10.02.2015 20:46:26: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:26: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:46:26: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:26: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:46:26: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:26: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:26: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:26: NibeRS485: Ignoring
10.02.2015 20:46:27: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:27: NibeRS485: Ignoring
10.02.2015 20:46:27: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:46:27: NibeRS485: Sending ACK
10.02.2015 20:46:27: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:46:27: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:27: NibeRS485: Sending ACK
10.02.2015 20:46:27: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:27: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:27: NibeRS485: Sending ACK
10.02.2015 20:46:27: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:27: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:27: NibeRS485: Ignoring
10.02.2015 20:46:27: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:27: NibeRS485: No data found with id 40004
10.02.2015 20:46:28: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:46:28: TaloLoggerThreadStore: Logged data for timestamp 20150210204625
dummy: 11.5
nibeoutdoor: 3.0
10.02.2015 20:46:28: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:28: NibeRS485: Ignoring
10.02.2015 20:46:28: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:28: NibeRS485: Sending ACK
10.02.2015 20:46:28: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:28: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:28: NibeRS485: Sending ACK
10.02.2015 20:46:28: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:28: NibeRS485: Received:
5C 00 20 68 50 93 9C 23 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0B 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 38

10.02.2015 20:46:28: NibeRS485: Sending ACK
10.02.2015 20:46:28: NibeRS485: Got data for id 40083: 0x0023
10.02.2015 20:46:28: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:28: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:46:28: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:28: NibeRS485: Got data for id 40079: 0x000B
10.02.2015 20:46:28: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:28: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:28: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:28: NibeRS485: Ignoring
10.02.2015 20:46:29: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:29: NibeRS485: Ignoring
10.02.2015 20:46:29: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:29: NibeRS485: Sending ACK
10.02.2015 20:46:29: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:29: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:29: NibeRS485: Sending ACK
10.02.2015 20:46:29: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:29: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:29: NibeRS485: Ignoring
10.02.2015 20:46:30: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:30: NibeRS485: Ignoring
10.02.2015 20:46:30: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:30: NibeRS485: Sending ACK
10.02.2015 20:46:30: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:30: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:30: NibeRS485: Sending ACK

10.02.2015 20:46:30: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:30: NibeRS485: Received:
5C 00 20 68 50 93 9C 23 00 94 9C 00 00 91 9C 13
00 92 9C 00 00 8F 9C 0B 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 38

10.02.2015 20:46:30: NibeRS485: Sending ACK
10.02.2015 20:46:30: NibeRS485: Got data for id 40083: 0x0023
10.02.2015 20:46:30: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:30: NibeRS485: Got data for id 40081: 0x0013
10.02.2015 20:46:30: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:30: NibeRS485: Got data for id 40079: 0x000B
10.02.2015 20:46:30: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:30: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:30: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:30: NibeRS485: Ignoring
10.02.2015 20:46:30: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:30: NibeRS485: No data found with id 40004
10.02.2015 20:46:31: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:31: NibeRS485: Ignoring
10.02.2015 20:46:31: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:31: NibeRS485: Sending ACK
10.02.2015 20:46:31: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:31: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:31: NibeRS485: No data found with id 40004
10.02.2015 20:46:31: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:31: NibeRS485: Sending ACK
10.02.2015 20:46:31: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:31: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:31: NibeRS485: Ignoring
10.02.2015 20:46:32: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:32: NibeRS485: No data found with id 40004
10.02.2015 20:46:32: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:32: NibeRS485: Sending ACK
10.02.2015 20:46:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:32: NibeRS485: Received:
5C 00 20 68 50 93 9C 33 00 94 9C 00 00 91 9C 19
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00

00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 20

10.02.2015 20:46:32: NibeRS485: Sending ACK
10.02.2015 20:46:32: NibeRS485: Got data for id 40083: 0x0033
10.02.2015 20:46:32: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:32: NibeRS485: Got data for id 40081: 0x0019
10.02.2015 20:46:32: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:32: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:46:32: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:32: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:32: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:32: NibeRS485: Ignoring
10.02.2015 20:46:32: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:32: NibeRS485: Sending ACK
10.02.2015 20:46:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:32: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:32: NibeRS485: Sending ACK
10.02.2015 20:46:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:32: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:32: NibeRS485: Ignoring
10.02.2015 20:46:32: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1F 00 00 00 8B

10.02.2015 20:46:32: NibeRS485: Sending ACK
10.02.2015 20:46:32: NibeRS485: Got queried data for id 40004: 0x001F
10.02.2015 20:46:32: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:32: NibeRS485: Sending ACK
10.02.2015 20:46:32: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:32: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:32: NibeRS485: No data found with id 40004
10.02.2015 20:46:33: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:46:33: TaloLoggerThreadStore: Logged data for timestamp 20150210204630
dummy: 11.5
nibeoutdoor: 3.1
10.02.2015 20:46:33: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:33: NibeRS485: Ignoring
10.02.2015 20:46:33: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:46:33: NibeRS485: Sending ACK

10.02.2015 20:46:33: NibeRS485: ERROR: Received unqueried or cancelled query data with 0x6A frame.

10.02.2015 20:46:33: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:33: NibeRS485: Sending ACK
10.02.2015 20:46:33: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:33: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:33: NibeRS485: Sending ACK
10.02.2015 20:46:33: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:33: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:33: NibeRS485: Ignoring
10.02.2015 20:46:34: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:34: NibeRS485: Ignoring
10.02.2015 20:46:34: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:34: NibeRS485: Sending ACK
10.02.2015 20:46:34: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:34: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:34: NibeRS485: Sending ACK
10.02.2015 20:46:34: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:34: NibeRS485: Received:
5C 00 20 68 50 93 9C 30 00 94 9C 00 00 91 9C 15
00 92 9C 00 00 8F 9C 0A 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2C

10.02.2015 20:46:34: NibeRS485: Sending ACK
10.02.2015 20:46:34: NibeRS485: Got data for id 40083: 0x0030
10.02.2015 20:46:34: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:34: NibeRS485: Got data for id 40081: 0x0015
10.02.2015 20:46:34: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:34: NibeRS485: Got data for id 40079: 0x000A
10.02.2015 20:46:34: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:34: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:34: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:34: NibeRS485: Ignoring
10.02.2015 20:46:35: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:35: NibeRS485: Ignoring

10.02.2015 20:46:35: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:35: NibeRS485: Sending ACK
10.02.2015 20:46:35: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:35: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:35: NibeRS485: Sending ACK
10.02.2015 20:46:35: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:35: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:35: NibeRS485: Ignoring
10.02.2015 20:46:35: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:35: NibeRS485: No data found with id 40004
10.02.2015 20:46:36: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:36: NibeRS485: Ignoring
10.02.2015 20:46:36: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:36: NibeRS485: Sending ACK
10.02.2015 20:46:36: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:36: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:36: NibeRS485: No data found with id 40004
10.02.2015 20:46:36: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:36: NibeRS485: Sending ACK
10.02.2015 20:46:36: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:36: NibeRS485: Received:
5C 00 20 68 50 93 9C 30 00 94 9C 00 00 91 9C 17
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2D

10.02.2015 20:46:36: NibeRS485: Sending ACK
10.02.2015 20:46:36: NibeRS485: Got data for id 40083: 0x0030
10.02.2015 20:46:36: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:36: NibeRS485: Got data for id 40081: 0x0017
10.02.2015 20:46:36: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:36: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:46:36: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:36: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:36: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:36: NibeRS485: Ignoring
10.02.2015 20:46:37: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:37: NibeRS485: Ignoring
10.02.2015 20:46:37: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:46:37: NibeRS485: Sending ACK
10.02.2015 20:46:37: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:46:37: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:37: NibeRS485: Sending ACK
10.02.2015 20:46:37: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:37: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:37: NibeRS485: Sending ACK
10.02.2015 20:46:37: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:37: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:37: NibeRS485: No data found with id 40004
10.02.2015 20:46:37: NibeRS485: Received:
5C 00 20 6D 0B 01 10 36 46 31 33 34 35 2D 32 34
0F

10.02.2015 20:46:37: NibeRS485: Sending ACK
10.02.2015 20:46:37: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:37: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:37: NibeRS485: Ignoring
10.02.2015 20:46:38: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:46:38: TaloLoggerThreadStore: Logged data for timestamp 20150210204635
dummy: 11.5
nibeoutdoor: 3.0
10.02.2015 20:46:38: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:38: NibeRS485: Ignoring
10.02.2015 20:46:38: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:38: NibeRS485: Sending ACK
10.02.2015 20:46:38: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:38: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:38: NibeRS485: Sending ACK
10.02.2015 20:46:38: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:38: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:38: NibeRS485: Ignoring
10.02.2015 20:46:39: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:39: NibeRS485: Ignoring
10.02.2015 20:46:39: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:39: NibeRS485: Sending ACK
10.02.2015 20:46:39: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:46:39: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:39: NibeRS485: Sending ACK
10.02.2015 20:46:39: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:39: NibeRS485: Received:
5C 00 20 68 50 93 9C 22 00 94 9C 00 00 91 9C 12
00 92 9C 00 00 8F 9C 0C 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 3F

10.02.2015 20:46:39: NibeRS485: Sending ACK
10.02.2015 20:46:39: NibeRS485: Got data for id 40083: 0x0022
10.02.2015 20:46:39: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:39: NibeRS485: Got data for id 40081: 0x0012
10.02.2015 20:46:39: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:39: NibeRS485: Got data for id 40079: 0x000C
10.02.2015 20:46:39: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:39: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:39: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:39: NibeRS485: Ignoring
10.02.2015 20:46:40: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:40: NibeRS485: Ignoring
10.02.2015 20:46:40: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:40: NibeRS485: Sending ACK
10.02.2015 20:46:40: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:40: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:40: NibeRS485: Sending ACK
10.02.2015 20:46:40: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:40: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:40: NibeRS485: Ignoring
10.02.2015 20:46:40: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:40: NibeRS485: No data found with id 40004
10.02.2015 20:46:41: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:41: NibeRS485: Ignoring
10.02.2015 20:46:41: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:41: NibeRS485: Sending ACK
10.02.2015 20:46:41: NibeRS485: Ignoring frame with unknown command in byte 4.

10.02.2015 20:46:41: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:41: NibeRS485: No data found with id 40004
10.02.2015 20:46:41: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:41: NibeRS485: Sending ACK
10.02.2015 20:46:41: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:41: NibeRS485: Received:
5C 00 20 68 50 93 9C 31 00 94 9C 00 00 91 9C 17
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2C

10.02.2015 20:46:41: NibeRS485: Sending ACK
10.02.2015 20:46:41: NibeRS485: Got data for id 40083: 0x0031
10.02.2015 20:46:41: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:41: NibeRS485: Got data for id 40081: 0x0017
10.02.2015 20:46:41: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:41: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:46:41: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:41: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:41: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:41: NibeRS485: Ignoring
10.02.2015 20:46:42: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:42: NibeRS485: Ignoring
10.02.2015 20:46:42: NibeRS485: Received:
5C 00 20 6A 06 44 9C 1E 00 00 00 8A

10.02.2015 20:46:42: NibeRS485: Sending ACK
10.02.2015 20:46:42: NibeRS485: Got queried data for id 40004: 0x001E
10.02.2015 20:46:42: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:42: NibeRS485: Sending ACK
10.02.2015 20:46:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:42: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:42: NibeRS485: Sending ACK
10.02.2015 20:46:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:42: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:42: NibeRS485: Ignoring
10.02.2015 20:46:42: NibeRS485: Running nibeBus query with id 40004
10.02.2015 20:46:42: NibeRS485: No data found with id 40004
10.02.2015 20:46:42: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:42: NibeRS485: Sending ACK
10.02.2015 20:46:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:42: NibeRS485: Received:
5C 00 20 EE 00 CE

10.02.2015 20:46:42: NibeRS485: Sending ACK
10.02.2015 20:46:42: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:43: TaloLoggerThreadStore: Storing logged data with 2 points.
10.02.2015 20:46:43: TaloLoggerThreadStore: Logged data for timestamp 20150210204640
dummy: 11.4
nibeoutdoor: 3.0
10.02.2015 20:46:43: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:43: NibeRS485: Ignoring
10.02.2015 20:46:43: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:43: NibeRS485: Sending ACK
10.02.2015 20:46:43: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:43: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:43: NibeRS485: Sending ACK
10.02.2015 20:46:43: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:43: NibeRS485: Received:
5C 00 20 68 50 93 9C 31 00 94 9C 00 00 91 9C 16
00 92 9C 00 00 8F 9C 09 00 90 9C 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 FF FF 00 00 FF FF 00 00 FF FF 00
00 FF FF 00 00 2D

10.02.2015 20:46:43: NibeRS485: Sending ACK
10.02.2015 20:46:43: NibeRS485: Got data for id 40083: 0x0031
10.02.2015 20:46:43: NibeRS485: Got data for id 40084: 0x0000
10.02.2015 20:46:43: NibeRS485: Got data for id 40081: 0x0016
10.02.2015 20:46:43: NibeRS485: Got data for id 40082: 0x0000
10.02.2015 20:46:43: NibeRS485: Got data for id 40079: 0x0009
10.02.2015 20:46:43: NibeRS485: Got data for id 40080: 0x0000
10.02.2015 20:46:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:43: NibeRS485: Got data for id 65535: 0x0000
10.02.2015 20:46:43: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:43: NibeRS485: Ignoring
10.02.2015 20:46:44: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:44: NibeRS485: Ignoring
10.02.2015 20:46:44: NibeRS485: Received:
5C 00 20 6B 00 4B

10.02.2015 20:46:44: NibeRS485: Sending ACK

10.02.2015 20:46:44: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:44: NibeRS485: Received:
5C 00 20 69 00 49

10.02.2015 20:46:44: NibeRS485: Sending ACK
10.02.2015 20:46:44: NibeRS485: Ignoring frame with unknown command in byte 4.
10.02.2015 20:46:44: NibeRS485: Received:
5C 00 29 90 00 B9

10.02.2015 20:46:44: NibeRS485: Ignoring
10.02.2015 20:46:45: NibeRS485: Received:
5C 00 29 55 02 08 00 76

10.02.2015 20:46:45: NibeRS485: Ignoring